

RECORD OF THOROUGH EXAMINATION OF LIFTING PLANT & EQUIPMENT

The Lifting Operations and Lifting Equipment Regulations 1998 Examination made in accordance with Regulations 9 (3) and 10 (1)

Description of Equipment & Manufacturer:		CASE 988 360° ROAD RAIL EXCAVATOR			
Identification Mark / Serial Number:		129079			
Plant No:		81			
Machine Hours:		5383			
40.1		William Bradshaw Portside North Ellesmere Port Cheshire CH65 2HQ			
Machine Location:		Ellesmere Port			
Date of last thorough examination & number:					
SWL (Kg):		QH S/NO - M9596 SWL - 10,000KG			
Advisory Defects:		NONE			
Date of thorough inspection:		20/06/2020			
DATE OF EXPIRY:		20/06/2021			
Declaration I hereby declare that the equipment in this record was thoroughly examined in accordance with the appropriate provisions and found free from any defect likely to affect safety other than those listed above on 20/06/2020.					
Inspecting Engineer:	Alex Reed	Alhe	2		
Authorised By:	Sam Garrity	St			

Record No:

Date of Record: 20/06/2020

AJH-BRA-190620/0013

Allan J Hargreaves Plant Engineers Ltd Longmeadow Lane Red Marsh Industrial Estate Thornton Cleveleys FY5 4JT

Date:	20/06/2020
Owner:	Allan J Hargreaves Plant Engineers Ltd / William Bradshaw / William Bradshaw
Item:	CASE 988 360° ROAD RAIL EXCAVATOR
Serial No:	129079



Plant No: 81 Location: Ellesmere Port

Machine Hours: 5383

Service Point Service Point 1. Cleanliness of machine 2. Visual check - structure for damage, signs of carcianjocrorisolon 3. Pivoting joints between bucket & dipper arm, the dipper arm and boom, boom and machine, for wear, corrosion, security, evidence of lubrication. 4. Operate and examine any telescopic extensions on the boom and dipper for wear and security. 4. Operate and examine any telescopic extensions on the boom and dipper for wear and security. 5. Check flexible hydraulic hoses for damage/leakage. 6. Check hydraulic cylinders for leakage, corrosion on the rods and dipper for wear and security. 7. Inspect Quick Hitch for wear, security, and lubrication. STATE sylva. 8. S/NO. 8. Check slewing mechanism for security and wear during change of reach of bucket. Check slew brake operation. 9. Check chessis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Deck means of access to ensure ladders, walkways, handralishand holds are complete and secure behaviorally and the security of t	Machine Hours: 5383						
Service Point 1. Clearliness of machine 2. Visual check - structure for damage, signs of cracking/corrosion. 3. Fivoling joints between bucket & dipper arm, the dipper arm and boom, boom and machine, for wear, corrosion, security, evidence of lubrication. 4. Operate and examine any telescopic extensions on the boom and dipper for wear and security. 5. Check flexible hydraulic hoses for damage/leakage. 6. Check hydraulic oylinders for leakage, corrosion on the rods and alignment. 7. Inspect Quick Hitch for wear, security and lubrication. STATE SWK & SINO - M9596 SWL - 10,000KG 8. Check slewing mechanism for security and wear during operation of slew motion on full range of movements and during change of reach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handralishand holds are complete and secure 12. Check tracks for wear, tension, sprockets and roilers (Tyre wear and Wheel nut loque/ condition) 13. Check seling mechanisms for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for over a diguards to ensure that access to trapping points is prevented. 15. Check coll and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and rearranting themselves the service of the season of the service of t							
1. Cleanliness of machine 2. Visual check - structure for damage, signs of cracking/corrosion 3. Pivoting joints between bucket & dipper arm, the dipper arm and boom, boom and machine, for wear, corrosion, security, evidence of lubrication. 4. Operate and examine any telescopic extensions on the boom and dipper for wear and security 5. Check flexible hydraulic cylinders for leakage, corrosion on the rods and alignment. 7. Inspect Quick Hitch for wear, security and lubrication. STATE SWL & SINO: 8. Check slewing mechanism for security and wear during operation of slew motion on full range of movements and during change of reach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handralishand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check reging covers and guards to ensure that access to trapping points is prevented. 16. Check to laid of their full elevels ensuring condition and level of fluid. 17. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check RCI System for operation i.e. Alarms, motion cuts and manipulator motion cut and manipulator motion	Service Point	Result	Remarks				
2. Visual check - structure for damage, signs of cracking/corrosions on 3. Pivoting joints between bucket & dipper arm, the dipper arm and boom, boom and machine, for wear, corrosion, security, evidence of lubrication. 4. Operate and examine any telescopic extensions on the boom and dipper for wear and security 5. Check flexible hydraulic hoses for damage/leakage. 6. Check hydraulic cylinders for leakage, corrosion on the rods and alignment. 7. Inspect Quick Hitch for wear, security and lubrication. STATE SYM. 8. SYNO. 8. Check silewing mechanism for security and wear during operation of slew motion on full range of movements and during change of reach of bucket. Check selw brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handralishand holds are complete and secure and Wheel nut torque / condition). 13. Check testing mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check tracking mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevented. 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 21. Check rose for peration i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell.	Service Point						
cracking/corrosion 3. Pivoting joints between bucket & dipper arm, the dipper arm and boom, boom and machine, for wear, corrosion, security, evidence of lubrication. 4. Operate and examine any telescopic extensions on the boom and dipper for wear and security 5. Check flexible hydraulic hoses for damage/leakage. 6. Check hydraulic cylinders for leakage, corrosion on the rods and alignment. 7. Inspect Quick Hitch for wear, security and lubrication. STATE SWM, & SNO. 8. Check slewing mechanism for security and ubrication. STATE SWM, & SNO. 9. Check slewing mechanism for security and wear during operation of slew motion on full frange of movements and during change of reach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handralis/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check sering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check of land other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system for operation i.e. Alarms, motion cuts and interlocking. RCI system for operation i.e. Alarms, motion cuts and interlocking. RCI system for operation	1. Cleanliness of machine	✓					
cracking/corrosion 3. Pivoting joints between bucket & dipper arm, the dipper arm and boom, boom and machine, for wear, corrosion, security, evidence of lubrication. 4. Operate and examine any telescopic extensions on the boom and dipper for wear and security 5. Check flexible hydraulic hoses for damage/leakage. 6. Check hydraulic cylinders for leakage, corrosion on the rods and alignment. 7. Inspect Quick Hitch for wear, security and lubrication. STATE SWM, & SNO. 8. Check slewing mechanism for security and ubrication. STATE SWM, & SNO. 9. Check slewing mechanism for security and wear during operation of slew motion on full frange of movements and during change of reach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handralis/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check sering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check of land other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system for operation i.e. Alarms, motion cuts and interlocking. RCI system for operation i.e. Alarms, motion cuts and interlocking. RCI system for operation	2. Visual check - structure for damage, signs of	,					
and boom. boom and machine, for wear, corrosion, security, evidence of lubrication. 4. Operate and examine any telescopic extensions on the boom and dipper for wear and security 5. Check flexible hydraulic cylinders for leakage, corrosion on the rods and alignment. 7. Inspect Quick Hitch for wear, security and lubrication. STATE SWL & S/NO: 8. Check slewing mechanism for security and wear during operation of slew motion on full range of movements and during change of reach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handrailshand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check expine covers and guards to ensure that access to trapping points is prevented. 16. Check in and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadverted roperation. 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check RCI System duty charts - check for accuracy with load cell. 21. Check RCI System for operation i. e. Alarms, motion cuts and interlocking. RCI system for operation i. e. Alarms, motion cut with load cell. 23. Check Operator visibility aids are working and in good							
evidence of lubrication. 4. Operate and examine any telescopic extensions on the boom and dipper for wear and security 5. Check flexible hydraulic hoses for damage/leakage. 6. Check hydraulic cylinders for leakage, corrosion on the rods and alignment. 7. Inspect Quick Hitch for wear, security and lubrication. STATE SWL & SINO. 8. Check slewing mechanism for security and wear during operation of slew motion on full range of movements and during change of reach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handrails/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition). 13. Check sleening mechanisms for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check sleening mechanisms for evidence of appropriate lubrication, security, damage and functionality checked during operation. 16. Check of and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and mans to prevent inadvertent operation and mans to prevent inadvertent operation. 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check RCI System for operation i. e. Alarms, motion cut and manipulator motion cut 22. Check RCI System for operation i. e. Alarms, motion cut and manipulator motion cut with load cell. 23. Check Operator visibility aids are working and ingood							
4. Operate and examine any telescopic extensions on the boom and dipper for wear and security 5. Check flexible hydraulic cylinders for leakage, corrosion on the rods and alignment. 7. Inspect Quick Hitch for wear, security and lubrication. STATE SWIL & S/NO: 8. Check slewing mechanism for security and lubrication. STATE SWIL & S/NO: 9. Check chased of bucket. Check slew brake operation. 9. Check chased of bucket. Check slew brake operation. 9. Check chases of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handrails/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check of and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation. 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check RGI System for operation i.e. Alarms, motion cuts and interlock operator visibility alds are working and in good		✓					
and dipper for wear and security 5. Check flexible hydraulic hoses for damage/leakage. 6. Check hydraulic olyinders for leakage, corrosion on the rods and alignment. 7. Inspect Quick Hitch for wear, security and lubrication. STATE SWL & S/NO: 8. Check slewing mechanism for security and wear during operation of silew motion on full range of movements and during change of reach of bucket. Check silew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handrails/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check enjine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation. 19. Visual exam windscreen and visual check for identification and means to prevent inadvertent operation. 19. Visual exam windscreen and liwindows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check foll operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation ie. Alarms, motion cuts and interlocking. RCI system for operation ie. Alarms, motion cuts and interlocking. RCI system for operation ie. Alarms, motion cuts and inter							
5. Check flexible hydraulic cylinders for leakage, corrosion on the rods and alignment. 7. Inspect Quick Hitch for wear, security and lubrication. STATE SWIN. & S/NO: 8. Check slewing mechanism for security and wear during operation of slew motion on full range of movements and during change of feach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handrails/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanisms for vidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation. 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, honn, lights etc. 21. Check RCI System for operation i.e. Alarms, motion cuts and interiocking. RCI system for operation i.e. Alarms, motion cuts and interiocking. RCI system for operation i.e. Alarms, motion cuts and interiocking. RCI system for operation and ingood		N/A					
6. Check hydraulic cylinders for leakage, corrosion on the rods and alignment. 7. Inspect Quick Hitch for wear, security and lubrication. STATE SWL & S/NO: 8. Check slewing mechanism for security and wear during operation of slew motion on full range of movements and during change of reach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handrails/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanisms for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check function i.e. Alarms, motion cuts and interlocking, RCl system for operation i.e. Alarms, motion cuts and interlocking, RCl system for operation i.e. Alarms, motion cuts and interlocking, RCl system for operation i.e. Alarms, motion cuts and interlocking, RCl system for operation i.e. Alarms, motion cuts and interlocking, RCl system for operation i.e. Alarms, motion cuts and interlocking. RCl system for operation i.e. Alarms, motion cuts							
and alignment. 7. Inspect Quick Hitch for wear, security and lubrication. STATE SWL & SINO: 8. Check slewing mechanism for security and wear during poration of slew motion on full range of movements and during change of reach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handralishand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Whele nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check function for peration it e. Alarms, motion cuts and interlocking. RCI system for operation it e. Alarms, motion cuts and interlocking. RCI system for poperation special control of electrical equipment, wipers, washers, with an analysis of the properation of the control of electrical equipment, wipers, washers, horn, lights etc. 22. Check RCI System for operation it e. Alarms, motion cuts and interlocking. RCI system for operation in good		√					
7. Inspect Quick Hitch for wear, security and lubrication. STATE SWL & S/NO: 8. Check slewing mechanism for security and wear during operation of slew motion on full range of movements and during change of reach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handralis/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 3. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 4. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check or traking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check function of peration i.e. Alarms, motion cuts and interlocking. RCl system for operation ii.e. Alarms, motion cuts and interlocking. RCl system for operation and ingood		✓					
SWL & S/NO: 8. Check slewing mechanism for security and wear during operation of slew motion on full range of movements and during change of reach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handralis/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation. 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut and interlocking. RCI system for operation ii. e. Alarms, motion cuts and interlocking. RCI system for operation in good							
SWL & S/NU. 8. Check slewing mechanism for security and wear during operation of slew motion on full range of movements and during change of reach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handralishand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut and interlocking. RCI system for operation ii.e. Alarms, motion cuts and interlocking. RCI system for operation and ingood		✓	S/NO - M9596 SWL - 10,000KG				
operation of slew motion on full range of movements and during change of reach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handrails/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut and interlocking, RCI system duty charts - check for accuracy with load cell.			,				
change of reach of bucket. Check slew brake operation. 9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handrails/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadventent operation 19. Visual exam windscreen and all windows for damage which affect visibility, and effectively without excessive play. Servo and manipulator motion cut 20. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 21. Check RC I System for operation i.e. Alarms, motion cuts and interlocking, RCI system duty charts - check for accuracy with load cell.							
9. Check chassis of vehicle for cracks, damage, corrosion. 10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handralis/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		ľ					
10. Check excavator arm or shovel loader arms for wear of pins and bushes. 11. Check means of access to ensure ladders, walkways, handralis/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good							
and bushes. 11. Check means of access to ensure ladders, walkways, handrails/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		·					
11. Check means of access to ensure ladders, walkways, handrails/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fittled) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operates smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		✓					
handrails/hand holds are complete and secure 12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good							
12. Check tracks for wear, tension, sprockets and rollers (Tyre wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		✓					
wear and Wheel nut torque / condition) 13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good							
13. Check steering mechanism for evidence of appropriate lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		✓					
lubrication, security, damage and wear by visual examination during operation. 14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good							
14. Check braking mechanisms for wear & adjustment, security, damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		✓					
damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good							
damage and functionality checked during operation. 15. Check engine covers and guards to ensure that access to trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		✓					
trapping points is prevented. 16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good							
16. Check oil and other fluid levels ensuring condition and level of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		✓					
of fluid. 17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good	trapping points is prevented.						
17. Visual check to ensure the fixing for driver's seat and restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		✓					
restraint (where fitted) are in place. 18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good							
18. Functional test of control levers for excessive wear, smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		✓					
smoothness of operation and visual check for identification and means to prevent inadvertent operation 19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good							
19. Visual exam windscreen and all windows for damage which affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		✓					
affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good							
affect visibility. 20. Check function of electrical equipment, wipers, washers, horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		1					
horn, lights etc. 21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		,					
21. Check full operation of machine to ensure all motions operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		✓					
operate smoothly and effectively without excessive play. Servo and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good							
and manipulator motion cut 22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		./					
22. Check RCI System for operation i.e. Alarms, motion cuts and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good		v					
and interlocking. RCI system duty charts - check for accuracy with load cell. 23. Check operator visibility aids are working and in good	22 Check RCI System for operation i.e. Alarms, motion cuts						
with load cell. 23. Check operator visibility aids are working and in good		✓					
23. Check operator visibility aids are working and in good							
		,					
	condition i.e. Mirrors, camera.	'					

		Key
I certify that the inspection has been completed to my satisfaction and the equipment is in a condition ready for work.		✓ Check / Inspection OK
		➤ Fault Found
		N/A Not Applicable
Completing Engineer:	Alex Reed	
Signature	Athee	