

6 MONTH -

ATTACHMENT INSPECTION CHECKSHEET

Customer: Bradshaw		Date: 23/1/19	
Machine manufacturer: Richter Muller brush		Machine Type: ballast broom	
P.O.V Number: 99709 000135-2		Serial Number:	
Plant Number: 114		SWL or WLL Displayed: NA	
Location: AJM		Initial boxes below when completed, mark N/A or X if fault found	
ID	Service Point		Fault Report and Further Action Required
1	Warning Decals	SS	
2	Retaining nuts and bolts	SS	
3	Retaining pins and clips	SS	
4	Operation	SS	
5	Lifting points	SS	
6	Lifting Chains	NA	
7	Inspect welds for cracks or defects	SS	
8	Hydraulic rotator operation	SS	
9	Hydraulic ram condition, leaks	SS	
10	Hydraulic leaks	SS	
11	Hydraulic hose condition	SS	
12	Hydraulic coupling condition	SS	
13	Fail safe lock valve operation	SS	
14	Grease all points	SS	
15	Documentation in machine & date	SS	
16	Check corner legs and lock pins	SS	
17	Security of all covers and panels	SS	
18	Attachment general condition	SS	

Inspecting Engineer:	Mark Inspecting Engineer N/A if no defects have been found
Signature:	

I certify that the inspection and rectification of defects found have been completed to my satisfaction and the machine is in a condition ready for work.

Completing Engineer: J. Stewart

Signature: *J. Stewart*

6 Month
 INSPECTION/SERVICE
 EXP 23/7/19

